

REPLACES

RH Leveling Box and Parts
(1939-64)

NCA577A
\$56.63

Right hand leveling box assembly. For all Ford tractors (1939-1964); except 501 & Majors. Also for 2000, 3000 (1965-1975).

9N595
\$1.74

Pin. For all tractors 1939-1964 (except Majors); for 2000, 3000, 4000 (1965 & up); 3600, 4600 (1975 & up).

957E566
\$8.37

Knuckle, RH leveling assembly. For all tractors 1939-1964 (except Majors); for 2000, 3000, 4000 (1965 & up); 3600, 4600 (1975 & up).

NCA579B
\$15.87

Shaft and gear, length 14"; thread length 4".

9N554
\$7.54

Bearing assembly.

9N594
\$7.29

Lever handle.

B9NN568A
\$6.81

Gear, leveling box pinion.

REPLACES

RH Box Assembly (1965 to
1983)

E0NN569AA
\$59.82

Box assembly, leveling RH. For tractors 2000, 3100, 3120, 3300, 3310, 3400, 3500, 4110 with dual category linkage (1965-1/1970); 334 less cab (1981-4/1983); 3610 less cab (1981-1982).

C5NN569AM
\$75.95

Box assembly, leveling RH, adjustment from 27-1/2" to 32". For tractors 3000, 4000, (1965-1975); 2600, 3600, 4600, 231, 233, 333 (1975-1981); 2310, 2610, 3610, 4610, 230A, 334, 335, 530A (1981-1991).

D2NN983AWF
\$171.30

Box assembly, leveling RH, adjustment is 26" to 32". For tractors 5000, 7000 (1965-1975); 5600, 5700, 6600, 6700, 7600, 7700 (1975-1981); 5610, 6610, 6710, 7610, 7710 (1981-1991).

REPLACES

Universal Economy Leveling
Assembly

LB152
\$44.28

Universal Economy Leveling Assembly. 1-5/16" body of high strength tubing, thread size, 7/8" fine thread-study clevis at each end with 5/8" pin holes. May be used right or left.

REPLACES

Left Hand Leveling Rod

9N564B
\$55.89

Rod and fork assembly, hydraulic lift, LH. For tractors 9N, 2N, 8N, NAA (1939-1954).

C5NNB863C
\$53.78

Leveling rod and yoke, LH. For tractors 5000, 7000 (1965-1975); 5600, 5700, 6600, 6700, 7600, 7700 (1975-1981); 5610, 5900, 6610, 6710, 7610, 7710, 7910 (1981-).

E4NNN673AA
\$30.95

Rod and yoke, LH. For tractors 3055, 3550, 4000 (except 4110) (1965-1975); 3600, 3600N, 4600SU (1975-1981); all purpose with Cat. I on 3910, 4110, 4610 (1981-); 4610SU (1981-1982). Replaces C5NNN673A.

C7NN564B
\$36.68

Leveling rod assembly, LH, adjustment is 21-3/4" to 24-3/4". For tractors 2000, 3100, 3120, 3300, 3310, 3400, 3500, 4110 w/dual category linkage (1965-1/1970); 334 L/cab (1981-4/1983); 3610 L/cab (1981-1982).

E0NNB484DA
\$73.44

Leveling rod assembly, LH, adjustment from 27-1/2" to 32". For tractors 3000, 4000 (1965-1975); 2600, 3600, 4600, 231, 233, 333 (1975-1981); 2310, 2610, 3610, 4610, 230A, 334, 335, 530A, (1981-1991).

C5NNB863CWKF
\$80.16

Leveling rod assembly, LH, adjustment is 27" to 33". For tractors 5000, 7000 (1965-1975); 5600, 5700, 6600, 6700, 7600, 7700 (1975-1981); 5610, 6610, 6710, 7610, 7710 (1981-1991).

REPLACES

Leveling Box Parts



9N585A
\$22.37

Fork, hydraulic lift leveling rod, RH. Length 10-1/4". For tractors 9N, 2N, 8N, NAA (1939-1954).

NCA585B
\$35.94

Fork, hydraulic lift leveling rod, RH. Length 14-3/4". For tractors 600, 800 (1955 & up); row crop HiClear (1957 & up).

E0NN585BA
\$35.94

Fork, hydraulic lift leveling rod, RH. Length 14" center hole to end 3/4" threads. For tractors 2000, 3000 (use with dual category linkage, 62" fork slot) (1965-1/1970); 3600 (1975-1981); 2310, 2610, 2810, 2910, 3610, Industrials 230A, 234, 334, 335, 530A, 62" fork slot (1981-). Can replace C5NN585D.

C5NN585B
\$50.37

Fork for leveling box. Length 20". For tractors 3055, 3550 series, 4000 (except 4110), 4140, 4200 (1965-1975).

E0NN585CA
\$74.61

Fork for leveling box. Length 20" thread 13/16"-12. For tractors 3900, 4100, 4600 (1975-1981); Cat. II on 4110, 4610 (1981-2/1990); industrials: 420, 515, 532, 535 (1975-1981). Replaces D3NN585A.

C5NN579F
\$19.83

Shaft with pinion gear. Length 12". FOR TRACTORS 2000 (EXCEPT 2300); 3100, 3120, 3310, 3400, 3500, 4110 (1965 & up); 3600, 4600 (1975 & up).

C5NN579E
\$19.83

Shaft with pinion gear. Length 12". for tractors 4000 (1965 & up), 4600 with cab (1975 & up).

E2NN579AA
\$31.56

Shaft with pinion gear. Length 14-5/8", thread 13/16"-12. For tractors 3900, 4100, 4600 (1975-1981); Cat. II, 4110, 4610 (1981-2/1990); Industrials 420, 515, 532, 535 (1975-1981).

REPLACES Forged Lower Lift Arm Assemblies



9N555B
\$49.52

Hydraulic lift arm. Heavy duty w/forged ball joint ends. Length 32". Painted Blue. For tractors 9N, 2N, 8N, NAA, right or left.

JSA1002R
\$46.05

Lower lift arm heavy-duty with forged ball-joint ends. Category 1 accommodates 7/8" drawbar or lower link pins. Painted red. Length 32". Replacement for Ford 9N555B right or left.

D0NN555DRH
\$55.56

Lower lift arm, RH, 5160 steel. 32" hole centers. For tractors 600, 800 (1955-1964); 2000, 3000, 2600, 3600 (1965-1981).

D0NN555CLH
\$55.56

Lower lift arm, LH, 5160 steel. 32" hole centers.

REPLACES Lower Link Support Pin

NCA563C
\$16.29

Lower link support pin. For tractors 8N, NAA, 600, 601, 800, 801, 1801, 2000, 4000, (1948 to 1964); row crop hi clearance: 700, 701, 900, 901, (1955 to 1964); 2000, 3000, 4000 without differential lock, (1965 to 1975); 3600, 4600, (1975 to 1981).

Lift Arm Repair End



LAS192
\$11.13

Lift arm repair end, bent, forged. Category I, 7/8" pin hole, 1-3/4" width at weld end. 5-1/4" overall length.

LAS292
\$14.97

Lift arm repair end, bent, forged. Category II, 1-1/8" pin hole, 1-3/4" width at weld end. 5-1/2" overall length.

REPLACES Lower Link Reducing Sleeves

EC0NG992AA
\$0.71

Sleeve bushing. Reduces 1-1/8" lift arm ball socket to accommodate 7/8" draw pin. 1-3/4" long.

P2004
\$0.69

Sleeve bushing. Reduces C5NN557B, ball to accommodate Cat. 1-7/8" draw pin. 1-3/8" long.

REPLACES Lift Arm Balls and Retainer Springs for 1965-75 & Up

DDN995233
\$4.35

Ball, lower link, 1-3/8" wide. Category I.

C5NN557A
\$4.08

Ball, lower link, 1-3/4" wide. Category II.

C5NN557B
\$4.34

Ball, 1-3/8" wide. Category II.

C5NNN557B
\$1.73

Spring, ball retainer. For dual-category lift arms.



REPLACES

Lower Link Pins



Replaces	Category	Pin Dia.	Useable Length	Overall Length	Thread Dia.	Adjustable Jam Nut	Fixed Shoulder
P70220 \$2.76	0	5/8"	1-1/8"	3-7/8"	5/8"		
P7221 \$3.38	I-0	7/8"	1-3/4"	4-1/2"	5/8"	Y	
251380 \$1.62	I	7/8"	1-3/4"	5-1/2"	7/8"		
251381F \$2.67	I	7/8"	2-1/2"	6-7/16"	7/8"		
251546F \$1.61	I	7/8"	1-3/4"	5-1/2"	7/8"		
251547 \$2.61	1	7/8"	2"	6-3/16"	7/8"		
P7212 \$4.35	II	1-1/8"	2"	6-5/16"	1-1/8"		Y
P2005 \$4.65	II	1-1/8"	1-3/4"	6-1/4"	1-1/8"	Y	
251382 \$3.35	II to I	1-1/8"	1-3/4"	5-1/4"	7/8"		
P6501 \$2.67	I	7/8"	2-1/2"	6-1/2"	7/8"		
251383 \$3.57	II to I	1-1/8"	2-1/4"	6-1/2"	7/8"		

REPLACES

Miscellaneous Pins



EC0E9
\$3.53

Linkage pin, 7/8" diameter, 3-3/4" usable length, 5" overall. For earth excavators E9, E10, E20, HD105, 205, 405.

JSA1200B
\$23.85

Top link, 16" body, combination Category II tractor & Category I implement ends. Adjusts 19-1/2" to 29-1/2" overall. Painted blue.

JSA2000B
\$25.88

Top link, 16" body, 1". Category II ball joints. Adjusts 21" to 33" overall. Painted blue.

TL162
\$21.59

Top link, 16" body, 1". Category II ball joints. Forged ends with 1-1/8" NC threads. Swedge steel center section. Adjusts 21" to 31" overall. Dichromate plated. Comparable to our JSA2000B & JSA2000R except body & ends are plated. Not available in colors.

REPLACES

Quality Forged Top Links

JSA1012C
\$17.12

Top link, 12" body, combination Category II tractor & Category I implement ends. Adjusts 16" to 24" overall. Dichromate plated.

JSA1000B
\$22.68

Top link, 16" body, 3/4". Category I ball joints. Adjusts 20-1/2" to 29" overall. Painted blue.

JSA1020B
\$20.94

Top link, 20" body, 3/4". Category I ball joints. Adjusts 25" to 35" overall. Painted blue.

JSA1024B
\$30.99

Top link, 24" body, 3/4". Category I ball joints. Adjusts 29" to 39" overall. Painted blue.

JSA1012-12C
\$26.69

Top link, 12" body, combination Category II tractor & Category I implement ends. Adjusts 16" to 24" overall. Dichromate plated.

JSA2024B
\$20.82

Top link, 24" body, 1". Category II ball joints. Adjusts 29" to 41". Painted blue.

JSA2020B
\$26.52

Top link, 20" body, 1". Category II ball joints. Adjusts 25" to 37". Painted blue.

REPLACES

Economy Forged Top Link

JSA5050
\$17.12

Top link 16" body. Category I, 3/4" ball joints. Adjust 20-1/2" to 29" overall. Dichromate plated center body. Replaces JSA5000.

JSA1111
\$7.32

Top link end, 1-1/8" right hand thread, Category I, 3/4" pin hole.

JSA1112
\$7.32 Top link end, 1-1/8" left hand thread, Category I, 3/4" pin hole.

REPLACES Heavy Duty Top Links



EC0N576AA
\$49.31 Category II heavy duty topline. 1-1/4" NC thread. Forged ends with 1" sockets. 16" body, , adjusts from 23" to 32" overall. Dichromate plated.

REPLACES Top Links & Repair Ends

D0NN576B
\$81.02 Top link, combination Cat. I & II, adjusts 24-1/2" to 34-1/2".

D0NN576A
\$80.67 Top Link, Cat. II both ends, adjusts 24-3/4" to 34-3/4".

DONNA911A
\$18.33 Cat. II RH threaded repair end.

DONNA914B
\$32.19 Cat. II LH threaded repair end.

DONNA914A
\$32.33 Cat. I LH threaded repair end.

P2007
\$0.71 Reducer bushing, Cat. II to Cat. I, 1-15/16" long, 1" O.D., 3/4" I.D.

REPLACES Heavy Duty Ratchet Top Link

TL175
\$110.04 Ratchet top link, 16" body. 1" Category II ball joints. Forged ends with 1-1/4" NC threads. Swedged steel center section. Adjusts 25-3/4" to 32-1/4" overall. Dichromate plated.



REPLACES Threaded Repair Ends

JSA1111
\$7.32 Top link end, 1-1/8" right hand thread, Category I, 3/4" pin hole.

RE1717L
\$14.37 Top link end, 1-1/4" left hand thread. Category II, 1" pin hole.

RE1718R
\$14.69 Top link end, 1-1/4" right hand thread, category II, 1" pin hole.

JSA1112
\$7.32 Top link end, 1-1/8" left hand thread, Category I, 3/4" pin hole.

TL10812RP
\$20.82 Top link end, 1-3/8" thread, right hand, 1-1/4" hole.

JSA2221
\$9.86 Top link end, 1-1/8" right hand thread. Category II, 1" pin hole.

TL10813LP
\$20.82 Top link end, 1-3/8" thread, left hand, 1-1/4" hole.

JSA2222
\$9.86 Top link end, 1-1/8" left hand thread. Category II, 1" pin hole.

REPLACES Weld-on Ball Sockets



B2226
\$5.96 Weld-on ball joint, 5/8" bore. Category 0.

BJ5418
\$5.99 Weld-on ball joint, 3/4" bore. Category I.

BJ5211
\$10.64 Weld-on ball joint, 1" bore. Category II.

B2229
\$14.13 Weld-on ball joint, 1-1/4" bore. Category III.

REPLACES Top Link Reducer Bushings



C7NNG993A
\$2.27 Reducer bushing, converts ball socket in top (center) link. From Cat. II to Cat. I.

B80209
\$0.69 Reducer bushing, 3/4" O.D. x 5/8" I.D. x 1-5/8" long. From Cat. I to Cat. 0.

B833
\$0.99 Reducer bushing, 2" overall length, 1-1/4" O.D., 1" I.D. From Cat. III to Cat. II.

REPLACES Forged Weld-on Repair Ends

- TLS310F**
\$6.65 Top link weld-on repair end. Plain finish, forged, 3/4" hole, Category I.
- TLS311F**
\$9.17 Top link weld-on repair end. Plain finish, forged, 1" hole, Category II.












REPLACES Combination Ball Sockets







- B2310**
\$32.72 Weld-on combination ball joint. For 5/8" or 3/4" pins. Category 0 or I.
- SBJ1**
\$11.40 Weld-on combination ball joint. For 3/4" or 1" pins. Category I or II.

REPLACES Top Link Pins

- 957E560**
\$0.98 Upper link pin. Pin, 3/4" dia., 3" usable length. Fits all models using Cat. I link with 3/4" hole. Supersedes 9N560.
- E381T9**
\$1.59 Pin, 3/4" dia. By 5" usable length. (Shoulder to pin hole center).
- E201GF9**
\$3.08 Top link pin, 1" dia. 5-5/8" eff. length. Cat. II.
- C5NN560A**
\$2.10 Upper link pin. For Major, 4000 (1965 & up).
- E27N995272**
\$2.49 Upper link pin. Fits Major diesel (4-15/16") (1952-1964).
- P70706**
\$0.93 Top link pin. Category O, 5/8" pin dia., 3" useable length. 4-1/2" overall length. Cat. 0.

REPLACES Stabilizer Kits & Parts





- F2040-LH**
Call for Price Left hand stabilizer kit. Stabilizer arm assembly w/bracket and U-bolts. For tractors 2910, 3910, 4110, 4610. 
- SK-IND**
\$210.62 Stabilizer kit. Contains 4 mounting brackets w/pins and 2-JSA5050 top links. Fits most 3-point hitches on light industrial models. 
- F3040LH**
Call for Price Left hand stabilizer kit, stabilizer arm assembly w/brackets and U-bolts. For tractors 5610, 6610, 7610, 7710, 8210. 
- 231253**
\$38.51 Complete kit, red. For tractors 9N, 2N, 8N, NAA, 600, 800. 
- F3040RH**
Call for Price Right hand stabilizer kit, stabilizer arm assembly w/brackets and U-bolts. For tractors 5610, 6610, 7610, 8210. 
- 230042R**
\$9.35 Arm only, red. Length 31-1/2". For tractors 9N, 2N, 8N, NAA, 600, 800. 
- F2040-RH**
Call for Price Right hand stabilizer kit. Stabilizer arm assembly w/bracket and U-bolts. For tractors 2910, 3910, 4110, 4610. 
- 231254R**
\$8.82 Universal bracket, right or left hand, red. Mounting bracket hole centers 5". 
- D9NNB856BB**
Call for Price Stabilizer arm assembly less brackets and U-bolts. For tractors 2910, 3910, 4110, 4610. 
- F3040-LB**
Call for Price Stabilizer outer tube & inner bar assembly, no brackets or U-bolts. Replaces Tisco stabilizer assemblies F3040LH or F3040RH. 
- 231253B**
\$36.69 Complete kit, blue. For tractors 9N, 2N, 8N, NAA, 600, 800. 
- F-LH**
Call for Price Bracket, left hand stabilizer. For tractors 2910, 3910, 4110, 4610. 

230042B \$9.35	Arm only, blue. For tractors 9N, 2N, 8N, NAA, 600, 800.	
F-RH \$30.00	Bracket, right hand stabilizer. For tractors 2910, 3910, 4110, 4610.	
F-UBOLT Call for Price	U-bolts. 2 required. For tractors 2910, 3910, 4110, 4610.	
231254B \$8.82	Universal bracket, right or left hand, blue. Mounting bracket hole centers 5".	
231253XHD \$61.56	Complete Kit: Extra heavy duty, using stabilizers, arms of alloy spring steel. For tractors 9N, 2N, 8N, NAA, 600, 800. Red.	
230042XHD \$24.02	Arm only, made of alloy spring steel, for kit 231253XHD, red only. 7/8" hole dia.	
SK23-6X \$66.83	Lift stabilizer kit. For universal Cat. I, tractors 2000, 3000, 4000 (1965 & up); 2600, 3600 (1975 & up); not for dual-category equipment.	
SKA6251 \$22.40	Left hand arm only for SK23-6X. 7/8" hole dia.	
SKA6252 \$22.40	Right hand arm only for SK23-6X. 7/8" hole dia.	

REPLACES Stabilizer Pins

C5NNN873A \$6.48	Stabilizer pin
251406F \$1.02	Stabilizer pin
230044-WNL \$1.02	Stabilizer pin
251385 \$3.66	Stabilizer pin
141185-WNL \$3.66	Stabilizer pin

Stabilizer Links

C5NN454B \$30.71	Link, stabilizer, RH. Cat. I & II. For tractors 3000 (except 3550) (1965-1975); 2600, 3600 (1975-1981); 4100, 4600SU (rigid - 1975-1981); 2610, 3610 (1981-); 4110, 4610SU (rigid - 1981-).	
C5NNN455B \$30.71	Link, stabilizer, LH. Cat. I & II. For tractors 3000 (except 3550) (1965-1975); 2600, 3600 (1975-1981); 4100, 4600SU (rigid - 1975-1981); 2610, 3610 (1981-); 4110 4610SU (rigid - 1981-).	
C5NN454C \$28.14	Link, stabilizer, RH. Cat. I only. For tractors 2000, 4110 (1965-1975); 3000 (except 3550) (11/1970-1975); 2600, 3600 (1975-1981).	
C5NNN455C \$28.14	Link, stabilizer, LH. Cat. I only. For tractors 2000, 4110 (1965-1975); 3000 (except 3550) (11/1970-1975); 2600, 3600 (1975-1981).	

REPLACES Stabilizer Chains

DCK1 \$28.83	Drawbar check chain kit. Contains 1 (pair) anchors, 2 eyelets, 2 chains, 4 clevis with pins and hardware.
CFPND936B-LB \$39.18	Single chain assembly; does not include brackets or U-bolt. For tractors 5000, 7000 (1965-1975); 5600, 6600, 6700, 7600, 7700 (1975-1981); 5610, 6610, 6710, 7610, 7710 (1981-).
CBPN598A \$5.88	Check chain & pin kit. Contains chain, two clevis with pins & cotters. For all tractors 1939-1964 (except Majors & 501).

APN582A Clevis with pin and cotter key.
\$1.11

REPLACES Eyelet Assemblies

NCB660A Eyelet assembly. For tractors 9N,
\$3.17 2N, 8N, NAA, 700, 900.



CEK3 Eyelet kit, includes eyelet
\$3.83 assembly, nut & lock washer.



NCA667A Eyelet check chain, RH.
\$4.59



NCA678A Eyelet check chain, LH.
\$4.59



REPLACES Drawbar Anchor & Safety Chain

957E5967 Anchor, Drawbar link check chain (pair). For
\$9.24 tractors 9N, 2N, 8N (1939-1952); NAA (1953-1954); 600, 700, 800, 900 (1955-1957); Dexta, Super Dexta (1958-1964); 2000, 4000 (1962-1964); 2000, 3000, 4000 (1965-1975); 2600, 3600, 4600 (1975-1981); 2610, 3610, 4610 (1981-2/1991). Replaces NCA597B.

9N5370 Chain, fixed drawbar safety chain assembly.
\$65.63 **EXACT of ORIGINAL.** For tractors: 9N, 2N, 8N, NAA (1939-1954).

REPLACES Standard Heat Treated Drawbars



9N5182HT Heat treated red standard drawbar. 30-1/2"
\$45.20 L hole center to hole center, 2-1/2" W, 1-1/8" thick.

9N5182HTB Heat treated blue standard drawbar. 30-1/2"
\$45.20 L hole center to hole center, 2-1/2" W, 1" thick.

DKN5182 Extra H.D. Heat treated drawbar, 1-1/2"
\$42.98 x 3" x 26", with Cat. II pins. (1-1/8"). For Major diesel.

REPLACES Economy Drawbars



9N5182A Standard red drawbar - 1" x 2-1/2" x 26", with
\$23.43 7/8" pins, (Category I).

9N5182B Standard blue drawbar - 1" x 2-1/2" x 26", with
\$23.43 7/8" pins, (Category I).

REPLACES Drawbar Stay Arms

9N5374 Upper arm, std: red. All models.
\$8.42

9N5375 Lower arm, std: red. All models.
\$8.42

9N5374B Upper arm, std: blue. All models.
\$8.36

9N5375B Lower arm, std: blue. All models.
\$8.46

REPLACES Swinging Drawbar Assembly



SDA6 Swinging drawbar assembly. Complete kit. For
\$97.94 8N, NAA, 600 series.

SDA8 Swinging drawbar assembly. Complete kit. For
\$122.25 tractors 800 series except 820, 821.

CONN805F Swinging drawbar. For SDA6, SDA8.
\$40.82

NCA803B Clevis assy. w/pins. For SDA6, SDA8.
\$28.25

NCA809A Drawbar hanger. For SDA6 kit.
\$43.22

NDA809A Drawbar hanger. For SDA8 kit.
\$53.84

PT3 Pin for clevis assembly.
\$3.78

REPLACES Swinging Drawbars



C5NN805C Swinging drawbar, 32-7/8" O.L. with 1-1/2"
\$92.99 offset. For tractors 2000, 3000 (except 3550) (1965-1975); 2600, 3600, 4100, 4600, 5600, 6600, 7600, 7700 (1975-1981); 2610, 2810, 2910, 3610, 3910, 4110, 4610, 230A, 530A (1981-2/1990); 3230, 3430, 3930, 4130, 4630 (3/1990-); 4830, 5030 (7/1990-).

C5NN805A \$106.89 Swinging drawbar 37-1/2" O.L. For tractors 5000, 7000 (1965-1975).



C5NN805J \$92.16 Swinging drawbar, 32-3/8" O.L. 540 rpm PTO. For tractors 2100, 3100 (1965-1975); 3900, 4100, 4600, 515, 532 (1975-1981); 2810, 2910, 3910, 4110, 4610 (1981-2/1990); 3230, 3430, 3930, 4130, 4630 (3/1990-); 4830, 5030 (7/1990-).

REPLACES Drawbar Clevis Pin & Spring

CBPN804A \$5.54 Kit, pin & spring clip. For tractors 2000, 3000, 4000 (1965 & up). Also services earlier models (1953-1964) using swinging drawbar.



C5NN807D \$2.48 Pin, swinging drawbar clevis.



311920 \$0.87 Spring clip.



REPLACES TISCO Hitch Pins with Hair Pin Lock



251537 \$2.78 5/8" X 4-1/2" hitch pin.

P6255 \$2.90 5/8" x 5-3/8" hitch pin.

251538 \$3.14 5/8" x 6-1/4" hitch pin.

251539 \$2.25 3/4 x 4-1/4 hitch pin.

P7505 \$3.51 3/4" x 5-1/4" hitch pin.

251540 \$2.67 3/4 x 6-1/4 hitch pin.

P8754 \$2.85 7/8" x 4-1/4" hitch pin.

251541 \$3.42 7/8 x 6-1/4 hitch pin.

P1004 \$5.57 1" x 4-1/4" hitch pin.

251542F \$5.72 7/8" x 6-1/4" hitch pin.

P1125 \$9.08 1-1/8" x 6-1/4" hitch pin.

P1250 \$10.85 1-1/4" x 6-1/4" hitch pin.

REPLACES Snap-Lock Spring Hitch Pins



EC0ND819JA \$6.51 3/4" dia. x 6-1/4" useable length.

REPLACES Agricultural Implement Linch Pins



DKLP91 \$0.15 Linch pin, 7/16" dia. pin x 1-3/4" useable length, 1-5/8" dia. ring.

DKP1/4 \$0.21 Linch pin, 1/4" O.D. pin x 1-1/4" long.

DKP3/16 \$0.21 Linch pin, 3/16" O.D. pin x 1-1/4" long.

DKP-SD-1 \$0.50 Special Duty Linch Pin, 7/16 x 11/32.2 long, ring I.D. 1-5/8. Requires twice the force to open.

DKPWCH \$0.59 Linch pin with ring & chain, 7/16" pin diameter, 1-5/8" long, 1-11/16" ring diameter. DKP pin with safety chain.



DKP-SL-1 \$1.46 Linch pin with safety lock ring, 7/16" dia. pin x 1-7/8" long, 1-11/16" ring dia.



REPLACES

Hair Pins



HP1
\$0.71

Hair Pin

HP2
\$0.65

Hair Pin

251413
\$0.32

3/16 diameter wire, 3-3/4 long.

251412
\$0.15

5/32 diameter wire, 2-15/16 long.

251411F
\$0.15

1/8 diameter wire, 2-9/16 long.

HP6
\$0.21

3/32 diameter wire, 1-5/8 long.

HP7
\$0.18

3/32" dia., wire, 1-3/16" long.


HP8
\$0.17

Hair Pin

150-piece assortment. Metal display rack for effective impulse sales is included.

REPLACES

(A) Loader-Backhoe Hydraulic Pumps



Replaces	PUMP APPLICATION	CAPACITY GPM @ RPM	DIA	TYPE	ROTATION	MOUNTING	INLET	OUTLET
192504 \$379.70	701, 702, 703 loaders	14 @2000	3/4"	Round with key	Left hand	Combo	1" NPT	3/4" NPT
195453 \$379.70	701, 702, late 703 loader	14 @2000	3/4"	Round with key	Left hand	Combo	1" NPT	3/4" NPT
7702425-29Z \$466.62	730 & 735 loaders	21.5 @ 2000	7/8"	13 spline	Left hand	2 bolt SAE "B"	1-5/8"-12 ORB	1-5/16"-12 ORB

REPLACES

Hydraulic Pumps for Ag & Industrial Applications

E1NN600AB
\$701.12

Hydraulic pump, gear type, engine mounted. For tractors 231, 233, 333, 335, 531, 2600, 3600 (1975-1981); 234, 2310, 2610, 3610 (1981-3/1983); 5610, 6610, 6710, 7610, 7710 (1981-9/1985). Replaces E1NN600AA.



D0NN600F
\$778.59

Hydraulic pump, gear type, mounted in center housing. For tractors with independent PTO; 3500, 4000, 4100, 4200, 4400, 4410, 4500 (1965-1975).



D0NN600G
\$797.69

Hydraulic pump, gear type, mounted in center housing. For tractors without dual power transmission: 5000, 7000 (1965-1975).



D8NN600KB
\$754.52

Hydraulic pump, gear type, mounted in center housing. For tractors 5600, 6600, 6700, 7600, 7700 (1975-1981). Replaces D8NN600KA.



E0NN600AC
\$887.72

Hydraulic pump, 9 gpm, gear type, mounted in center housing. For tractors 5610, 6610, 6710, 7610, 7710 (1981-10/1991); 5900 (12/1987-10/1991); 7810, 7910, 8210 (2/1988-10/1991); 5610S, 6610S, 7610S, 7810S (1/1994). Replaces E0NN600AB.



D5NN600C
\$930.56

Hydraulic Pump, 16 gpm. For tractors 8000, 8700, 9000, 9700 (1968-1978).

**L827-10X**
\$379.70

Pump assembly, 14 GPM. Includes pump, foot/flange bracket, 2 mounting bolts & washers, and 2 adapters. For various loaders mounted on Ford tractors. For complete specifications see pump number 192504 on pump chart. Replaces 3660.

L827-10X-LB
\$276.87

Pump less bracket, includes 2 adapters.

**33020-1**
\$109.14

REPLACES

Hydraulic Pump Repair Parts for 9N, 2N, 8N

HPOK1
\$302.01

pump repair kit. Contains cam blocks, pistons, chamber kits, PTO shaft bushing, safety valve, and gaskets.

9N621KIT
\$27.21

Repair kit for hydraulic pump chamber.

9N617A
\$56.96

Cam block, for hydraulic pump.

9N615
\$38.76

Piston, for hydraulic pump.

9N649A
\$23.42

Bushing for hydraulic pump base, for PTO shaft.

REPLACES

Hydraulic Piston Type Pump Repair Kits

**CCPN600AB**
\$40.23

Repair kit. Services 1953 thru 1964 four cylinder gas or diesel tractors with piston type pump. For tractors NAA, 501, 600, 601, 700, 701, 800, 801, 900, 901, 2000, 4000. Will service either NCA600C or NCA 600F pump. Replaces CCPN600A & CCPN600B.

FHPK600-4
\$38.10

Minor repair kit for 4.3 gpm piston type pump. For tractors 2000, 4110 (1965 & up); except independent PTO. Services C5NN600-AB.

FHPK600-5
\$37.91

Minor repair kit for 5.6 gpm piston type pump. For tractors 3000, 4000 (except 4110) (1965 & up); except independent PTO. services C5NN600-AA.

CKPN600A
\$68.16Major repair kit. **For tractors:** 2000, 3000, 4000 (except independent PTO) (1965 & up); 2600, 3600, 4600 (1975 & up); also LCG, utility & industrial models. Services engine mounted pumps C5NN600AA, C7NN600Y, C5KNN600AB, & C7NN600Z (1965 & up); D4NN600C & D6NN600A (1975 & up).

REPLACES

Hydraulic Piston Type Pump Parts

NCA966E
\$53.88

Shaft. For 4-cyl tractors (1953-1964) using NAA600D or NCA600F pump assemblies.

C3NN908A
\$22.07

Main gear for piston pump. For tractors NAA, 600, 700, 800, 900, 2000, 4000 series (thru 1964).

D5NN1201A
\$4.26

Cone. For NCA966E shaft. (LM67048).

D5NN1202A
\$1.89

Cup, outer bearing. For NCA966E shaft. (LM67010).

NCA881A
\$5.57

Needle bearing assy. pump hsg. For all tractors (1953-1964); except Majors.

C5NN966A
\$52.74

Shaft. For tractors 2000, 3000, 4000 exc. Ind. PTO (1965 & up); 2600, 3600, 4600 (1975 & up).

C0DW4621A
\$9.00

Bearing cone. For C5NN966A shaft. (M86649)

C0DW4616A
\$3.92

Bearing cup. For C5NN966A shaft. (M86610)

169024
\$5.43

Bearing assembly, needle. For C5NN966A shaft.

22258X
\$5.94

Ball bearing, double shielded, I.D. 0.9843", O.D. 2.0472", W. 0.5906". For pump shaft D1NN966A. For tractor 4500 with Vickers Vane-type pump.

REPLACES

Pump Shaft Oil Seal

C5NN851A
\$5.67

Hydraulic pump shaft oil seal. I.D. 0.9350", O.D. 2.004", W. 0.5315". For tractors NAA, 600, 700, 800, 900, 2000, 4000 series (1953-1964). Can replace NCA851A, D8NN851AA.

REPLACES

Hydraulic Pump Gaskets & Kits

**FPN910B**
\$6.21

Piston type hydraulic pump gasket & O ring kit. For all tractors 1953 & up.

9N611 \$1.43	Gasket, hydraulic pump base to center housing. For tractors 9N, 2N, 8N (1939-1942).
9N613 \$1.46	Gasket, valve chamber to base. For tractors 9N, 2N, 8N (1939-1942).
NAA867A \$1.07	Gasket, piston pump cover, outer. For tractor NAA.
D6NN867A \$1.14	Gasket, piston pump cover, outer. For all tractors 1955 & up.
CONN869A \$0.75	Gasket, piston pump cover, inner. For all tractors 1953 & up (except 620, 820).
EAF911B \$0.51	Gasket, piston pump, gear housing to engine. For all tractors 1953 & up.
NAA17382A \$0.24	Gasket, proofmeter drive bushing. For piston pumps (1953 & up); vane pumps (1955).
CAPN503B \$1.20	Lift cover o-ring kit. NAA models after S/N 20900.
CKPN485A \$2.66	Lift cover o-ring kit. For 600, 700 800, 900, 2000, 4000 series.

REPLACES Hydraulic Pump Control and Safety Valves

9N640 \$36.26	Hydraulic pump control valve. For tractors 9N, 2N.	
8N638 \$31.49	Valve assy. For tractors 9N, 2N, 8N.	
NAA638E \$50.97	Valve assy. For tractors NAA (1953-1954).	
NCA638C \$56.07	Valve assy. For tractors 600, 700, 800, 900, 2000, 4000 (1955-1964).	
C7NN638E \$70.98	Relief valve, for hydraulic pump. For piston or gear type in center housing. For tractors 2000, 3000, 4000, 5000, 7000 (1965-1975).	

(B) Pump Drive Couplings Chain Type

54C1067
\$60.45

Coupling half, #40 chain sprocket, 16 tooth. Bore 1" dia., 6 spline. Used on Sherman 54B & 54C loader pump drive.

REPLACES

(B) Pump Drive Couplers



L601-14
\$48.06

Coupler Complete, Morflex Series 302. Contains center member, 2 drive flanges with set screws, and 4 bolts with lock nuts.

Center member. (A) 3-1/8" dia.; (B) four 1/4" holes, 1-15/16" spacing.

191061
\$12.62

Drive flange; 3/4 round bore with set screw 1/4" x 3/8" #SSH4-6.

L36-4
\$53.58

Drive flange; 5/8" round bore with set screw 1/4" x 3/8" #SSH4-6.

L36-5
\$53.58

Drive flange; 7/8" round bore with set screw 1/4" x 3/8" #SSH4-6.

L601-9
\$64.70

Morflex Series 352 coupler complete with 2 drive flanges, set screws, 4 bolts & lock nuts.

192169
\$36.57

Center member. (A) 3-5/8" dia.; (B) four 5/16" holes, 2-1/4" spacing.

192199
\$12.11

Drive flange; 3/4" round bore with set screw 1/4" x 3/8" SSH4-6.

L36-6
\$56.93

Drive flange; 5/8" round bore with set screw 1/4" x 3/8" #SSH4-6.

L36-8
\$56.93

Drive flange; 7/8" round bore with set screw 1/4" x 3/8" #SS4-6.

L36-19
\$56.93

Drive flange; 1" round bore with set screw 1/4" x 3/8" #SS4-6.

L78-13
\$27.20

Drive flange, 13 spline for 7/8" dia. shaft. 5/16" dia. bolt holes 2-1/4" on center.

REPLACES

(C) Hydraulic Pump Shafts



SEE NEXT PAGE FOR PRICES

Replaces	APPLICATION	SHAFT DIAMETER	SHAFT OVERALL LENGTH	END A TYPE	END A SIZE	END B TYPE	END B SIZE
197118	720 Loader	3/4"	8-3/8"	Key	3/4"	10 Spline	1"
195454	1953-64 Ford except 1808 & 4140	3/4"	9-3/8"	Key	3/4"	10 Spline	1"
194355	NAA, 600, 800	3/4"	9-1/4"	Key	3/4"	6 Spline	3/4"
194354	9N, 2N, 8N	3/4"	13"	Key	3/4"	6 Spline	3/4"
190760	9N, 2N, 8N	3/4"	13-1/16"	Key	3/4"	LH Thread	5/8"
292222	730 Loader	7/8"	10-3/8"	13 Spline	7/8"	13 Spline	7/8"
7701044	730 Loader	7/8"	11-5/8"	13 Spline	7/8"	13 Spline	7/8"
291951	730 Loader	7/8"	13-5/8"	13 Spline	7/8"	13 Spline	7/8"
7707570							
290481	730, 735 Loader	3/4"	8-7/8"			10 Spline	1"
C5NNA932C	535, 450 Ind. Tractors	NA	11-5/8"	4 bolt hub	13 Spline	7/8"	
E0NNA932AB	Ford Industrials Tractors	N/A	7-1/4"	4 bolt hub	13 spline	7/8"	
	445, 445A, 545, 545A						

REPLACES

Hydraulic Pump Hubs & Sheaves



SEE NEXT PAGE FOR PRICES

Replaces	APPLICATION	CENTER BORE	HUB O/A DIA	MOUNT HOLES QTY. & DIA.	MOUNT HOLES: TYPE	HOLE SPACING	RELIEF DIA	RELIEF DEPTH	RELATED PARTS
191196	9N, 2N 8N	5/8" LH thread	3"	no holes 4 pins 11/32"	smooth	2-13/32"			190760 shaft
192161	9N, 2N 8N	3/4"-6 spline	3-3/8"	4, 1/4"	smooth	2-3/8"	1-1/4"	7/16"	192160 sheave, 194354 shaft
54C2055	Sherman 54 Series Loader	3/4"-6 spline	3-7/8"	4, 7/16"	smooth	2-3/4"	1-1/2"	7/16"	194354 shaft, or 194355 shaft
291061	730 Loader	7/8"-13 spline	4"	4, 7/16"	smooth	2-3/4"	1-1/2"	7/16"	291951, 292222, 7701044 shafts
C5NNN879A	730 Loader	7/8"-13 spline	5-1/4"	4, 7/16"	smooth	3-7/8"	1-9/16"	3/4"	291951, 292222, 7701044 shafts
291315	730 Loader	7/8"-13 spline	5-1/4"	4, 7/16"	threaded	3-7/8"	1-9/16"	7/16"	291951, 292222, 7701044 shafts
290421	1953-64 Ford except 1808 & 4140	1"-10 spline	4"	4, 7/16"	smooth	2-3/4"	1-3/8"	9/16"	195454 shaft

F-6-216-A

HYDRAULIC PUMP SHAFTS

197118	\$35.91
195454	\$32.42
194355	\$24.68
194354	\$25.10
190760	\$13.32
292222	\$33.29
7701044	\$43.43
291951	\$26.24
7707570	\$28.43
290481	\$76.80
C5NNA932C	\$189.41
E0NNA932AB	\$149.09

HYDRAULIC PUMP HUBS & SHEAVES

191196	\$33.36
192161	\$37.83
54C2055	\$30.72
291061	\$43.37
C5NNN879A	\$53.94
291315	\$51.54
290421	\$43.37

REPLACES

Quadrant Stop Kit

QSK3FF
\$5.75

Improved unit. Quadrant stop kit, includes wing nut 350890S36 and flat washer. Replaces 9N521. Fits all models (1939-1964); except Majors.

REPLACES

Hydraulic Lift Cover Repair Kit

LCRK928
\$9.15

Lift cover repair gasket kit. For tractors 9N, 2N, 8N.

**LCRK53/54**
\$6.34

Hydraulic lift cover repair kit. For tractors NAA (1953 to 1964).

**LCRK55/64**
\$8.39

Hydraulic lift cover repair kit. For 1955 to 1964 tractor models: 501, 600, 601, 700, 701, 800, 801, 900, 901, 2000, 4000.

**LCRK65UP**
\$10.34

Kit. For tractors 2000, 3000, 4000 (1965 & up).

**LCRK57**
\$22.37

Master repair kit, for hydraulic lift cover. For tractors 5000, 7000 (1965-1975).

**C5NNA967B**
\$10.46

Gasket, hydraulic lift cover. For tractors 5000, 7000 (1965-1975).



REPLACES

Parts for Ford Hydraulic Lift

9N510D
\$104.42

Hydraulic lift cylinder. For tractors 9N, 2N, 8N.

**9N530B**
\$22.53

Piston, hydraulic lift. For tractors 9N, 2N, 8N. Optional with NAA530B when used with o-ring NAA533A & washer NAA473A.

**9N675**
\$6.68

Rings, steel, kit of three. For piston 9N530B.

**NAA530B**
\$20.33

Piston o-ring type. For tractor NAA (1953-1954). Optional for 9N, 2N, 8N when used with o-ring NAA533A & NAA473A.

**NAA533A**
\$0.62

O-ring for hydraulic lift piston. For tractor NAA.

**NAA473A**
\$1.67

Back-up washer for lift piston NAA530B.

NCA473A
\$1.83

Back-up washer for piston NCA560B. For tractor 2000, 3000 (except 3550) (1955-1964); 4114 (1965 & up).

NCA533A
\$0.71

O-ring, 87111S95, for hydraulic lift piston NCA530B. (1955-1964).

9N531C
\$14.42

Rocker shaft bushing, 2 used. I.D. 2.000", O.D. 2-3/8", L. 3.00". For all tractors (1939-1964); 2000, 3000 (except 3550), 4110 (1965-11/1971).

**C5NN486F**
\$2.52

Pin, hydraulic lift yoke. O.D. 1.00", usable length 4-3/8". For tractor Major 4000 (1965 & up).

**9N550**
\$4.89

Special lock washer, hydraulic lift shaft to arm. For tractors: 9N, 8N, NAA (1939-1954).

9N529
\$2.43

Felt, hydraulic lift draft control spring seat. For tractors: 9N, 2N, 8N, NAA, 600, 601, 700, 701, 800, 801, 900, 901, (1939-1962).

8N486B
\$9.66

Pin, hydraulic lift yoke. For tractors: 8N, NAA, Jubilee, (1950-1954).

2N624
\$7.25

Seat, hydraulic lift draft control spring. EXACT of ORIGINAL. For tractors: All (1939 to 1964).
Seat, hydraulic support lift draft control spring. **EXACT of ORIGINAL.** For tractors: 9N, 2N, 8N, NAA, Jubilee, 501, 600, 700, 800, 900, 2000, 4000, (1939 to 1964).

352625S8
\$4.44

Hydraulic lift rocker pin to rear end housing. (3/4 x 3.14). EXACT of ORIGINAL. For tractors: 9N, 2N (1939 to 1947).

REPLACES

Hydraulic Lift Parts



87111S95
\$0.71

O-ring hydraulic lift piston. For tractors 2000, 3000 (1965-1975); 2600, 3600 (1975-1981); 2610, 3610 (1981-). Replaces NCA533A.

NCA473A
\$1.83

Back-up washer for piston NCA560B. For tractor 2000, 3000 (except 3550) (1955-1964); 4114 (1965 & up).

C5NN533A
\$0.90

O-ring, for lift cylinder piston. For tractors 4000 (1965-1975).

D1NN473A
\$4.79

Ring, back-up, for lift cylinder piston. For tractors 4000 (1965-1975). Replaces C5NN473A.

373408S
\$1.17

O-ring, for lift cylinder piston. For tractors 5000, 7000 (1965-1974). For 3.75" diameter piston in tractors 5600, 5700, 6600, 6700, 7600, 7700 (1975-1981).

REPLACES

Lift Cover O Ring Kits



CAPN503B
\$1.20

Lift cover o-ring kit. NAA models after S/N 20900.

CKPN485A
\$2.66

Lift cover o-ring kit. For 600, 700 800, 900, 2000, 4000 series.

REPLACES

Safety Valve for Lift Cylinder



DDN984
\$21.39

Safety valve. For hydraulic lift cylinder on tractors Fordson Major (11/1960-1964); 4000 (except 4110); 5000, 7000 (1965-1979).

REPLACES

Hydraulic Lift Cover & Pump Repair Kit

B5001
\$7.49

O-ring kit for lift cover & pump. For tractors 2000, 3000, 4000, 5000, 7000 (1965-1975).

REPLACES

Hydraulic Lift Housing Cover Gaskets



9N502
\$1.68
NAA502A
\$2.13
NCA502A
\$1.46

Hydraulic lift housing. For tractors 9N, 2N, 8N.

Hydraulic lift housing cover. For tractors NAA.

Hydraulic lift housing cover. For tractors 1955-1964 (except Majors).

C5NN502A
\$2.24

Hydraulic lift cover. For tractors 2000, 3000, 4000 (1965 & up).

C5NN518B
\$1.02
2N516B
\$19.14

Disc, lift lever friction. For tractors (1939 & up).

Friction plate for hydraulic lift lever control. Use with disc C5NN518B. For tractors 1939 to 1964. Replaces 2N516A, 2N516A2.

9N523B
\$0.69
9N552
\$0.20

Lower link support plate. For tractors 9N, 2N.

Cylinder to center housing cover. For tractors 9N, 2N, 8N.

NAA552A
\$0.30

Cylinder to center housing cover. For tractors NAA (1953-1954).

9N553
\$0.47

Hydraulic lift cylinder housing. For tractors 9N, 2N, 8N.

NAA553B
\$0.42

Hydraulic lift cylinder housing, R.H. For tractors NAA.

REPLACES

Attachment Cylinder for Wagner



WAG8-51
\$230.91

Economy double acting attachment cylinder. Replaces H800-51. 2-1/2" bore, 17-3/4" stroke, 26-12" closed, 3/4" clevis pin.

1C4759
Call for Price

Kit: seals & o-rings.

REPLACES

Hydraulic Cylinder Seal Kits

HSK2002

Seal Kit, for 2" bore HTL & HSL Series top and side link cylinders. Contains seals and o-rings for 2" cylinder repair, (Ref. A). For cylinders - HTL2101, HTL2102, HTL2103, HSL2201, HSL2202, HSL2203. Kit HSK2002 replaces old kit HSK2001.

HSK3002

Seal Kit, for 3" bore HTL & HSL Series top and side link cylinders. Contains seals and o-rings for 3" cylinder repair. For cylinders-HTL3101, HTL3101M, HTL3102, HTL3102M, HTL3103, HTL3103M, HTL3105, HTL3105M, HTL3106, HTL3106M, HSL3201, HSL3201, HSL3201M, HSL3202, HSL3203, HSL3203M. Kit HSK3002 replaces old kit HSK3001.

REPLACES

Cylinder Packing Kits for Backhoes & Loaders



309949

Seal, Packing

309940

Seal, Packing

309946

Seal, Packing

309939

Seal, Packing

309948

Seal, Packing

309957

Seal, Packing

251165

Seal, Packing

309959

Seal, Packing

REPLACES

Cylinder Packing Kits for Wagner



L609-94

Cylinder packing kit. For H800-31, 32, 39, 45, 49, 54, 55, 59, 62, 63, 67.

L609-104

Cylinder packing kit. For H800-5, 55000CR.

L609-145

Cylinder packing kit. For H800-51, 85, 87, 89, 90, 92, 93, 94, 95, 100.

REPLACES

Hydraulic Hose Assemblies

HV4970

Hose, 18".

DGPNB950S1-KIT

Kit assembly, includes 1-spool valve (non-detent/spring centering), hoses, dust cover, couplers, handle & valve mounting kit.

E4NNB968BB

Hose, valve to coupler, 1-wire braid. 3/8" I.D. x 25", 9/16"-18 ORB male swivel 90° M, 6[degree] M elbow one end x 3/4"-16 ORB male solid other end. Use with TISCO B950 valves when using OEM 3/4" ORB female coupler half.

HV4958

Hose, 46".

HV4959

Hose, 48".

HV4971

Hose, 21".

DGPNB950S2-KIT

Kit assembly, includes 2-spool valve (non-detent/spring centering), hoses, dust cover, couplers, handle & valve mounting kit.

HV4972

HV4961

Hose, Hose Assembly
1/4 NPT Male solid

DGPNB950K1-KIT

Kit assembly, includes 1-spool valve (pressure detent), hoses, dust cover, couplers, handle & valve mounting kit.

HV4962

Hose, Hose Assembly
1/4 NPT male solid

HV4973

DGPNB950K2-KIT

Kit assembly, includes 2-spool valve (pressure detent), hoses, dust cover, couplers, handle & valve mounting kit.

E1NNB950AB

Valve, single-spool, (non-detent/spring centering) less handle.

H31-SPL-30

Hose, 30".

HV4964

Hose, Hose Assembly
1/4 NPT male solid

E1NNB950BB

Valve, double-spool, (non-detent/spring centering) less handle.

HV4966	Hose, Hose Assembly 1/4 NPT Male solid
H31-SPL-36	
HV4967	Hose, Hose Assembly 1/4 NPT
D9NNB950BB	Valve, single-spool, pressure detent, less handle.
292838	Hose, 24" overall length, 3/8" I.D., 1 wire braid, 100 R1-AT, 3/8" NPT male 90° swivel x 3/8" NPT female solid. Fits 730 loader.
E2NNB950CA	Valve, double-spool, pressure detent, less handle.
HV4976	Hose, 39".
H31-SPL-26	Hose
HV4977	Hose, 44".
8250-4	Coupler
HV4978	Hose, Hose Assembly 1/4 NPTM solid
9006-4	Double break-away clamp.
HV4979	Hose, Hose Assembly 1/4 NPTM solid
HV4980	Hose, Hose Assembly
9507-4-1H	Automatic dust covers.
D6NND916D	Bracket, hose coupler.
HV4981	Hose, Hose Assembly 1/4 NPTM solid
HV4982	Hose, Hose Assembly
309972F	Handle & valve mounting kit, single-spool.
309973F	Handle & valve mounting kit, single-spool.
D3NNB936A	Handle with blue vinyl coated grip, for 1 & 2 spool valves.
DHPN485A	O-ring kit, valve mounting.
C9NND912A	Pivot for hydraulic control valve handle.
D2NNH889A	Pivot bolt for handles.

C9NNH891A	Nut for pivot bolt.
721FSO-3/8	
HV8510	Bolt, valve mounting, 7/16" -14 x 1-1/4".
7/16-14X3-3/4	
HV4908	Bolt, valve mounting, 7/16" -14 x 2-1/2".
WH06U-L06	

REPLACES

Hose Assemblies for Loaders & Backhoes



D8NND558EA	Hose, valve bank to cylinders (6 used). Fits backhoes 735, 750, 755.
292838	Hose, 24" overall length, 3/8" I.D., 1 wire braid, 100 R1-AT, 3/8" NPT male 90° swivel x 3/8" NPT female solid. Fits 730 loader.
292841	Lift cylinder extension hose, 24" overall length, 3/8" I.D., 1 wire braid 100 R1-AT, 7/8"-14 ORB male swivel x 7/8"-14 37° swivel x 3/8" NPT female solid. Fits 735 loader.
7701142	Hydraulic hose assembly. For use on 740 series loaders. 24" bucket cylinder hose. Models include 19-421, 19-450, and 19-451. 4 hoses used on each model.

REPLACES

Hose Connector



CU878FO	for pipe thread hydraulic hose. On 713 & 723 backhoes. Female 1/2" NPT to male special Ford thread and o-ring tube extension.
----------------	---

REPLACES

Hydraulic Coupler Tips & Adaptors



8010-4P

Male tip, poppet style, has a 1/2" NPT thread. Can replace Ford hydraulic tips D7NNB964A, D5NNB964A, D3NNB964A, D3NNJ964A, D1NNB964A, C9NNB964A, C9NNB964B, C7NNB964A. Used on 6X & 6Y series 7000-9000 (1965 & up); 7 Ag & Industrial (1975 & up); 8000, 9000, TW10, TW20, TW30 (1968 & up). Replaces 5090-4.

S25-4-3D

Hydraulic adapter. Adapts John Deere male tip to Ford female coupler.

4065-4L

Long adapter. John Deere to Ford.

D5NNB964A

Male tip-check valve assembly, implement half. Replaces Ford poppet-type assembly & OEM D3NNB964AA, D1NNB964A, C9NNB964B tips; fits tractor series 2000-9000 (1965 & up); D5NNB964A on tractor series 2600-9700 (1975 & up); TW10, TW20, TW30 (1979 & up).

4075-4L

Specially designed long adapter. I.H.C. to Ford.

REPLACES

Hydraulic Coupler Kit



HV4298

Coupler kit, for 4000 series valves. Contains: 2 quick couplers (S20-4), 2 hoses, 44 (H31-SPL-44), double break-away clamp (S24-4), quick-cover assembly (HV4957).

S20-4

Quick coupler, 2 each.

H31-SPL-44

Hose, 44".

S42-4

Double break-away clamp. For use with S20-4 and S40-4 couplers. Quik-cover assembly HV4957 fits this clamp.

HV4957

Quick-cover assembly. For Safeway (S42-4) and Pioneer double breakaway clamp assemblies.

REPLACES

Remote Hydraulic Valves and Valve Parts



These valves and valve parts are for late model Ford tractor applications (Ag and Industrial). The valves bolt directly to tractor top hydraulic cover in place of the accessory plate. Control handles are operated from RH side of operators seat. Tisco kits include valve, handle & mounting kit (handle, pivot bolt & nut, mounting bolts, o-ring & seal kit). Control handle grip is coated with blue heavy durable vinyl which is molded to cast metal handle.

Application: The valves listed below can be used on the following model (Ag & Industrial) tractors: 500 thru 900 (1955 thru 1961); 2000 thru 4000 (USA production thru 1964); 2000 thru 5000 (1965 to 1975); 2600 thru 6600 (1975 to 1981); 2610, 3610, 4610, equipped with single pump hydraulic system, (1981 to -).

Complete Kit	Valve	Handle Kit	Description
E1NNB950AB-KIT	E1NNB950AB	309972F	Kit assembly, includes single spool valve (non-detent/spring centering) and handle & valve mounting kit
E1NNB950BB-KIT	E1NNB950BB	309973F	Kit assembly, includes double spool valve (non-detent/spring centering) and handle & valve mounting kit
D9NNB950BB-KIT	D9NNB950BB	309972F	Kit assembly, includes single spool valve (pressure detent) and handle & valve mounting kit
E2NNB950CA-KIT	E2NNB950CA	309973F	Kit assembly, includes double spool valve (pressure detent) and handle & valve mounting kit

REPLACES

Handle Kits Contents

Replaces	Description	Qty in 309972F	Qty in 309973F
HV4908	BOLT	2	2
7/16-14X3-3/4	CAPSCREW	2	2
HV8510	CAPSCREW	2	2
C9NNH891A	NYLOC SCREW NUT	1	2
DHPN485A	O-RING KIT	1	1
D3NNB936A	VALVE HANDLE	1	2
D2NNH889A	VALVE PIN	1	2

REPLACES

Remote Hydraulic Valve Kits With Hose & Couplers



For late model Ford tractor applications (Ag and Industrial). These kits include valve, hoses, hose couplers & coupler bracket, self-closing dust covers and handle mounting kit. Valves are of current OEM design and bolt directly to tractor top hydraulic cover in place of accessory plate. Control handles are operated from RH side of operators seat.

Application: These valves can be used on the following model (Ag and Industrial) tractors: 500 thru 900 (1955 thru 1961); 2000 thru 4000 (USA production thru 1964); 2000 thru 5000 (1965 to 1975); 2600 thru 6600 (1975 to 1981); 2610, 3610, 4610, equipped with single pump hydraulic system, (1981 to -).

Complete Kit	Valve	Handle Kit	Description
DGPNB950S1-KIT	E1NNB950AB	309972F	Kit assembly, includes single spool valve (non-detent/spring centering), hoses, dust cover, handle & valve mounting kit
DGPNB950S2-KIT	E1NNB950BB	309973F	Kit assembly, includes double spool valve (non-detent/spring centering), hoses, dust covers, couplers, handle & valve mounting kit
DGPNB950K1-KIT	D9NNB950BB	309972F	Kit assembly, includes single spool valve (pressure detent), hoses, dust cover, couplers, handle & valve mounting kit
DGPNB950K2-KIT	E2NNB950CA	309973F	Kit assembly, includes double spool valve (pressure detent), hoses, dust covers, couplers, handle & valve mounting kit

REPLACES

Replaces	Description	Qty in			
		DGPNB950S1-KIT	DGPNB950S2-KIT	DGPNB950K1-KIT	DGPNB950K2-KIT
8250-4	BODY HALF FEMALE	2	4	2	4
D6NND916D	BRACKET HYD	1	1	1	1
9006-4	CLAMP	1	2	1	2
9507-4-1H	DUST COVER	1	2	1	2
H31-SPL-26	HYD HOSE ASSY	2	4	2	4

REPLACES

Deluxe Remote Hydraulic Valve Kits



Built in Mexico, model 5900 was introduced in the USA in May, 1985. In May 1986, the hydraulic lift cover was upgraded to the Series-10 design. Our deluxe Remote Hydraulic Valve Kits will fit the 5900 tractors with the upgraded (Series-10) hydraulic lift cover. Application: Ford 5900 tractors (5-1987 to -).

HV5920

Kit assembly, includes 2-spool valve, valve box with handles.

HV5930

Kit assembly, includes 3-spool valve, valve box with handles.

Replaces	Description	Qty in	
		HV5920	HV5930
D6NND916D	BRACKET HYD	1	1
9006-4	CLAMP	2	3
9507-4-1H	DUST COVER	2	3
2H10120RF140RM	HCA264 ADAPTOR	1	1
HV4897	HOSE 30 INCH	1	1
HV4898	HOSE 40 INCH	1	1
H31-SPL-30	HYD HOSE ASSY	2	2
H31-SPL-44	HYD HOSE ASSY	2	4
HV4992	VALVE BOX	1	0
HV4993	VALVE BOX	0	1

REPLACES

Remote Hydraulic Valve Kit for Ford 20-Series Tractors (Japan)



- HV4118** Kit assembly, includes 1-spool valve with handle.
- HV4124** Kit assembly, includes 2-spool valve with handles
- HV4125** Kit assembly, includes 2-spool valve, valve box with handles.


Replaces	Description	Qty in	Qty in	Qty in
		HV4118	HV4124	HV4125
5006-4	CLAMP DOUBLE	1	2	2
4250-4	COUPLER	2	4	4
60UB-06X06	HSA12 ADAPTOR	2	2	2
60SB-06X06	HSA2 ADAPTOR	1	1	1
HV4945	HYD ADAPTER PLATE	1	1	1
H31-SPL-30	HYD HOSE ASSY	2	4	4
HV4959	HYD HOSE ASSY	3	3	3
HV4020	HYDRAULIC VALVE KIT	0	1	0
HV4940	POWER PLUG KIT	1	1	1
HV4957	QUIK-COVER	1	2	2
HV4984	VALVE BOX	0	0	1

REPLACES

Remote Hydraulic Valve Kits for Ford Tractors (Japan)

The remote valve kits are complete with hoses, quick-couplers, clamps and Tisco quick-covers. Two versions are being offered; Economy and Deluxe. The Deluxe Kit also includes valve box and H.D. handles.

Application: Ford Tractor Models 1700, 1900, 1710, 1910 & 2110 (Japan).





HV4116	Economy kit assembly, includes 1-spool valve with handle. Tractors less Draft control
HV4126	Economy kit assembly, includes 2-spool valve with handles. Tractors less Draft control
HV4127	Deluxe kit assembly, includes 2-spool valve, valve box with handles. Tractors less Draft control
HV4117	Economy kit assembly, includes 1-spool valve with handles. Tractors WITH Draft control
HV4128	Economy kit assembly, includes 2-spool valve with handles. Tractors WITH Draft control
HV4129	Deluxe kit assembly, includes 2-spool valve, valve box with handles. Tractors WITH Draft control

Replaces	Description	Qty in	Qty in	Qty in	Qty in	Qty in	Qty in
		HV4116	HV4126	HV4127	HV4117	HV4128	HV4129
HV4950	ADAPT PLATE KIT	1	1	1	0	0	0
5006-4	CLAMP DOUBLE	1	2	2	1	2	2
4250-4	COUPLER	2	4	4	2	4	4
HV4907	HYD ADAPTER KIT	0	0	0	1	1	1
HV4958	HYD HOSE ASSY	1	1	1	1	1	1
HV4959	HYD HOSE ASSY	1	1	1	1	1	1
HV4970	HYD HOSE ASSY	1	2	2	1	2	2
HV4971	HYD HOSE ASSY	1	2	2	1	2	2
HV4957	QUIK-COVER	1	2	2	1	2	2
HV4984	VALVE BOX	0	0	1	0	0	1

REPLACES

HV4000 Series Remote Hydraulic Valve Kits

Application: Ford Tractor Models 500 thru 6600, U.K. & U.S.A., with single pump hydraulic system (1955 thru 1981).



HV4111

Kit assembly, includes 1-spool valve with handle.

HV4120

Kit assembly, includes 2-spool valve with handle.

HV4121

Kit assembly, includes 2-spool valve with handle (has float on one spool).

HV4122

Kit assembly, includes 2-spool valve, valve box with handles.

Replaces	Description	Qty in	Qty in	Qty in	Qty in
		HV4111	HV4120	HV4121	HV4122
S42-4	CLAMP	1	2	2	0
5006-4	CLAMP	0	0	0	2
	DOUBLE				
4250-4	COUPLER	0	0	0	4
S40-4	COUPLER	2	4	4	0
60SB-06X06	HSA2	2	2	2	0
	ADAPTOR				
H31-2M-12	HYD HOSE ASSY	2	2	2	0
HV4970	HYD HOSE ASSY	1	2	2	2
HV4971	HYD HOSE ASSY	1	2	2	2
HV4976	HYD HOSE ASSY	0	0	0	1
HV4977	HYD HOSE ASSY	0	0	0	1
292838	LBP HOSE ASSY	2	2	2	0
HV4957	QUIK-COVER	1	2	2	2
HV4992	VALVE BOX	0	0	0	1
HV4902	VALVE PLATE KIT	1	1	1	1

REPLACES

Hydraulic Cylinder Kits For Ford 20 Series

Application: Ford tractor models: 1320 (10-1987 to -), 1520 (10-1987 to -), 1720 (10-1987 to -), 1920, 2120, (Japan).



HCKF292

2-spool valve and cylinder kit complete.

HCKF293

3-spool valve and cylinder kit complete.

Replaces	Description	Qty in	
		HCKF292	HCKF293
60UB-06X06	HSA12 ADAPTOR	2	2
60SB-06X06	HSA2 ADAPTOR	1	1
HV4945	HYD ADAPTER PLATE	1	1
HV4959	HYD HOSE ASSY	3	3
HV4961	HYD HOSE ASSY	2	2
HV4962	HYD HOSE ASSY	1	3
HV4964	HYD HOSE ASSY	1	1
HSL2203	HYD SIDE LINK	1	1
HTL2102	HYD TOP LINK	1	1
HV4940	POWER PLUG KIT	1	1
HV4984	VALVE BOX	1	0
HV4985	VALVE BOX	0	1
HV4023	VALVE LESS HANDLE	1	0
HV4033	VALVE LESS HANDLE	0	1

REPLACES

Hydraulic Cylinder Kits

Application: Ford Tractor Models 1700, 1900, 1710, 1910 & 2110 (Japan).

HCKF192D

Draft control equipped tractors, 2-spool valve kit complete.

HCKF193D

Draft control equipped tractors, 3-spool valve kit complete.

HCKF192R

Regular (no draft control), 2-spool kit complete.

HCKF193R

Regular (no draft control), 3-spool kit complete.

Replaces	Description	Qty in	Qty in	Qty in	Qty in
		HCKF192D	HCKF193D	HCKF192R	HCKF193R
HV4950	ADAPT PLATE KIT	0	0	1	1
HV4907	HYD ADAPTER KIT	1	1	0	0
HV4958	HYD HOSE ASSY	1	1	1	1
HV4959	HYD HOSE ASSY	1	1	1	1
HV4961	HYD HOSE ASSY	2	2	2	2
HV4962	HYD HOSE ASSY	1	1	1	1
HV4964	HYD HOSE ASSY	1	1	1	1
HV4966	HYD HOSE ASSY	0	1	0	1
HV4967	HYD HOSE ASSY	0	1	0	1
HSL2203	HYD SIDE LINK	1	1	1	1
HTL2102	HYD TOP LINK	1	1	1	1
HV4984	VALVE BOX	1	0	1	0
HV4985	VALVE BOX	0	1	0	1
HV4023	VALVE LESS HANDLE	1	0	1	0
HV4033	VALVE LESS HANDLE	0	1	0	1

REPLACES

Hydraulic Cylinder Kits

Application: Ford Tractor Models 500-900 (55-60); 2000-4000 (USA-1964), 2000-5000 (65-75); 2600-6600 (75-81), Industrials 230-545. With single pump hydraulic system.

Not for Ag 10-Series or Industrial C or D-Series tractors



HCKF262

2-spool valve and cylinder kit complete.

HCKF263

3-spool valve and cylinder kit complete.

Replaces	Description	Qty in	
		HCKF262	HCKF263
HV4976	HYD HOSE ASSY	1	0
HV4977	HYD HOSE ASSY	1	1
HV4978	HYD HOSE ASSY	2	2
HV4979	HYD HOSE ASSY	1	1
HV4980	HYD HOSE ASSY	1	1
HV4981	HYD HOSE ASSY	0	1
HV4982	HYD HOSE ASSY	0	1
HSL3201	HYD SIDE LINK	1	1
HTL3101	HYD TOP LINK	1	1
HV4992	VALVE BOX	1	0
HV4993	VALVE BOX	0	1
HV4023	VALVE LESS HANDLE	1	0
HV4033	VALVE LESS HANDLE	0	1
HV4902	VALVE PLATE KIT	1	1

REPLACES

HV5902

Hydraulic Adapter Kit

Adapter kit. Can replace OEM adapter plate 9613790. Adapter plate in HV5902 kit features three ports: (1) pressure port, (1) power-beyond port and (1) return port. All ports 3/4" - 16 ORB. Kit contains adapter plate, o-rings, mounting bolts, plugs, and instructions. For models with single-pump hydraulic system, tractors 500-900 (1955-1960); 2000, 4000 (USA-1964); 2000-5000 (1965-1975); 2600-6600 (1975-1981); industrials 230-545. Not for AG 10 series, 5900 produced after April 1986, or industrial C- or D-series tractors.



HV4902

Adapter plate kit. Contains 1-HV4901 adapter plate, mounting cap screws, o-rings and mounting instructions. For tractors with single-pump hydraulic system 500-900 (1955-1960); 2000-4000 (USA-1964); 2000-5000 (1965-1975); 2600-6600 (1975-1981); industrials 230-545.



HV4907

Adapter plate kit, tractors with draft control on 3-pt. hitch. This is a 2-port adapter P-pressure and R-Return. Ports are 9/16"-18 ORB thread. Kit contains o-ring seals, 1-60UB 06X06 90E swivel fitting, metric hardware, and mounting instructions. For Ford (Japanese) 1710, 1910, and 2110 tractors.



HV4950

Adapter plate kit, tractors without draft control on 3-pt. hitch. Kit contains adapter, o-ring seals, metric hardware, and mounting instructions. This is a 2-port adapter. All ports are 9/16-18 ORB thread. For Ford (Japanese) 1710, 1910, and 2110 tractors.



REPLACES

HV4992

Valve Box & Handle Kits

Valve box. Two-handle assembly, vertical mount. Constructed as HV4984 and HV4985. Handles are designed to allow easy, comfortable operation of all valve spools. Designed to mount on vertical fender surface to the right of operator's seat. Installed and field tested on 35 hp and up Ford utility tractors. Will accommodate HV4023 valve (or equivalent size valve).



HV4984

Valve box assembly with handles installed, top mount. 2 handles, all steel (14-gauge). Unit has built-in handle pivots complete with actuator links and two 3/8" dia. steel handles; one straight and one offset. With durable plastic knobs. Removeable cover with edge protectors for operator protection. Will accommodate HV4023 valve (or equivalent size valve). Designed to mount on top of flat top fenders.



HV4985

Valve box with 3 handles installed. One straight handle in center position flanked by two offset handles. Will accommodate HV4033 valve (or equivalent size valve).



HV4993

Valve box. Three-handle assembly, vertical mount. Will accommodate HV4033 valve (or equivalent size valve).



REPLACES

HV4910

Valve Components & Optional Kits











Handle kit. Includes handle & mounting kit with hardware. For all standard HV4000 Series valves.



HV4911

Handle Mounting Kit. Includes bail & hardware for mounting the HV4910 standard handle.



HV4917	Handle Kit, same as HV4910 except has special bracket used for 90° rotated handle. Replaces HV4912.		HV4941	Closed Center Plug Kit. Can be installed in HV4000 valve in place of Allen Head Plug in side of valve casting. Allows use of valve with closed center hydraulic system (such as late John Deere with variable displacement hydraulic pump).		
HV4916	90° Handle Mounting Kit, includes bracket and hardware for mounting the HV4917 90° handle kit. Replaces HV4913.		REPLACES Hydraulic Valves			
HV4923	Spool Seal Kit. Front & rear spool sealing o'rings. For use with full range of HV4000 valves.		HV4023	Valve, 2-spool, 2000 psi. Relief, tandem (4-way) spool, spring center to neutral, less handles.		
HV4930	Float Spool Detent Kit. Contains all parts needed to convert standard spool to float spool. An exclusive feature of the HV4000 Series Valves-you can convert a tandem action (4-way) spool to float detent merely by installing the HV4930 kit. Other valve manufacturers require a special valve body or spool for float operation - this cannot be field installed. The HV4000 can be converted in the field. One important exclusion, on any two spool valve, only one spool can be equipped with a float detent.		HV4033	Valve, 3-spool, 2000 psi. Relief, tandem (4 way) spool, spring center to neutral, less handles.		
HV4931	Standard Spring Center Kit. Standard equipment on any valve equipped with spring centering spool control. Kit contains all parts needed to repair or convert existing spool.		REPLACES Replacement Handles and Parts			
HV4932	Three Position Detent Kit (no spring). Any tandem action spool can be converted to detent using this kit. Spool will remain in detented position until physically moved to neutral. Not a pressure release detent kit.					
HV4931	Standard Spring Center Kit. Standard equipment on any valve equipped with spring centering spool control. Kit contains all parts needed to repair or convert existing spool.			HV4988	Handle, offset. Used in HV4984 & HV4895. (Ref. 1)	
HV4932	Three Position Detent Kit (no spring). Any tandem action spool can be converted to detent using this kit. Spool will remain in detented position until physically moved to neutral. Not a pressure release detent kit.			HV4989	Handle, straight. Used in HV4984 & HV 4895. (Ref. 2)	
HV4940	Power beyond plug kit. Can be installed in HV4000 valve in place of allen head plug in side of valve casting. Allows plumbing additional hydraulic control valve into system.			HV4990	Handle, short angled. Used in HV4992 & HV4993. (Ref. 3)	
				HV4998	Handle, medium angled. Used in HV4992 & HV4993. (Ref. 4)	
				HV4999	Handle, long angled. Used in HV4992 & HV4993. (Ref. 5)	
				HV4987	Knob. Used with handles HV4988, HV4989, HV4990, HV4999. (Ref.6)	
			HV4975	Link Kit, valve handle actuator. Used with handles HV4988-HV4999. (Ref. 7)		

REPLACES

One Spool Valves



HV4010

Valve with handle, single-spool, 2000 psi. Relief, tandem (4-way) spool, spring center to neutral. For small to medium sized tractors, domestic and imports.

HV4012

Valve, hydraulic, with handle, single-spool multi-valve. No relief, tandem (4-way) spool, convertible to 3-way, spring center to neutral, with 90° rotated handle. For small to medium sized tractors, domestic and imports.

REPLACES

Two Spool Valves



HV4020

Valve with handles, two-spool, 2000 psi. Relief, tandem (4-way) spool, spring center to neutral. For small to medium sized tractors, domestic and imports.

HV4021

Valve with handles, two-spool, 2000 psi. Relief, one-spool tandem (4-way) float position with spring center to neutral and one spool tandem (4-way) spring center to neutral. For small to medium sized tractors, domestic and imports.

REPLACES

Three Spool Valves



HV4030

Valve with handles, three-spool, 2000 p.s.i. Relief, all spools tandem (4-way) spring center to neutral. For small to medium sized tractors, domestic and imports.

REPLACES

Popular O Ring Seals



NAA533A

O-ring for hydraulic lift piston. For tractor NAA.

13-OR

O-ring for hydraulic pump relief plug. 11/16" ID x 7/8" OD.

7A-OR

O-ring for pressure line plug. 3/8" ID x 1/2" OD.

212-OR

O-ring, plate assembly to lift cover. 1-1/8" ID x 1-1/4" OD.

361-OR

O-ring, plate assembly to lift cover. 1-3/4" ID x 1-7/8" OD.

356-OR

O-ring, hydraulic pump body (vane type pump). 2-1/2" ID x 2-5/8" OD.

11-OR

O-ring, power steering return line union. Replaces LA33604A. 9/16" ID x 3/4" OD.

87004S94

1/4" I.D. 1/16" thick.

87006S94

Plate assembly to lift cover.

87010S94

Lift cylinder to lift cover, hydraulic pump relief valve body.

87012S94

Plate assembly to lift cover.

87020S94

O-ring, fuel valve body. For gas tractors 501, 600, 601, 700, 701, 2000 (1955-1964); 800, 801, 900, 901, to S/N 126524 with 1/4" fuel line (1955-1960). For diesel tractors 501, 601, 701, 801, 901, 2000, 4000 (1958-1964).

8-OR

O-ring, check valve plug. 3/8" ID x 9/16" OD.

87033S94

Inlet tube and exhaust tube.

87034S94

Plate assembly to lift cover.

87035S94

Pressure tube to center housing.

87036S94

11/16" I.D. 3/32" thick.

87051S94

O-ring, intake tube to valve pump. For 4-speed transmission models.

87053S94





Pump flow control valve.

87055S94	O-ring intake tube to manifold sidemount. For tractors 8N 1950 & up, side mount.
25-OR	O-ring, 1-3/8" ID x 1-5/8" OD.
106-OR	O-ring, 2-1/4" ID x 2-1/2" OD.
109-OR	O-ring, 2-5/8" ID x 2-7/8" OD.
114-OR	O-ring, 3-1/4" ID x 3-1/2" OD.
115-OR	O-ring, PTO shaft bearing retainer. 3-3/8" ID x 3-5/8" OD.
121-OR	O-ring, steering gear side cover. 4-1/8" ID x 4-3/8" OD.
87111S95	O-ring hydraulic lift piston. For tractors 2000, 3000 (1965-1975); 2600, 3600 (1975-1981); 2610, 3610 (1981-). Replaces NCA533A.

REPLACES O-Ring Kit and Display Merchandiser

ORD382 O-ring kit and display merchandiser.

Replaces	Description	Qty in ORD382
1-OR	O-RING	20
10-OR	O-RING	13
11-OR	O-RING	13
12-OR	O-RING	13
13-OR	O-RING	13
14-OR	O-RING	13
15-OR	O-RING	10
16-OR	O-RING	10
17-OR	O-RING	10
18-OR	O-RING	10
19-OR	O-RING	10
2-OR	O-RING	20
20-OR	O-RING	10
21-OR	O-RING	10
22-OR	O-RING	10
23-OR	O-RING	10
24-OR	O-RING	10
25-OR	O-RING	10
26-OR	O-RING	10
27-OR	O-RING	10
28-OR	O-RING	7
29-OR	O-RING	7
3-OR	O-RING	20
30-OR	O-RING	7
4-OR	O-RING	20
5-OR	O-RING	20
6-OR	O-RING	20
7-OR	O-RING	20
8-OR	O-RING	13

Replaces	Description	Qty in ORD382
9-OR	O-RING	13
REPLACES	Hydraulic Top Link Cylinders	
		
HTL2102	Hydraulic top link cylinder, 2" bore.	
HTL3101	Top link cylinder.	
HTL3103	3" bore.	
REPLACES	Hydraulic Side Link Cylinders	
		
HSL2201	Hydraulic side link cylinder, 2" bore.	
HSL2203	Side link cylinder, 2".	
HSL3201	Side link cylinder.	
REPLACES	Accessory Items	
HV4957	Quick-cover assembly. For Safeway (S42-4) and Pioneer double breakaway clamp assemblies.	
S42-4	Double break-away clamp. For use with S20-4 and S40-4 couplers. Quik-cover assembly HV4957 fits this clamp.	
REPLACES	S.O.S. Pipe Dope	
PDT300	Roll, in self-dispenser, 1/2" tape, 300 inches long.	

REPLACES

Hydraulic Pump Hubs &
Sheaves

192152

Pulley supplied with four rubber bushings for hub with 11/32" pins when used with front mounted loader.

192160

Pulley has four 1/4"-20 threaded holes for hub when used with front mounted loader.