

MISCELLANEOUS

REPLACES

Patent Data Plates and Screws

9N14001
\$7.85

Patent data plate, with drive screws to install. For tractors: 9N, 2N, {1939-1947}.



8N14001
\$7.85

Patent data plate, with drive screws to install. For tractors: 8N, {1948-1952}.



8N14002S
\$0.60

Patent data plate drive screws {set of 4}. For tractors: 9N, 2N, 8N {1939-1952}.



REPLACES

Running Board Bracket & Parts

8N16487
\$33.42

Bracket, rear running board. **LH** side. **EXACT of ORIGINAL. For tractors;** 8N (1948 TO 1952), NAA (1953 TO 1954).

8N16486
\$36.20

Bracket, rear running board. **RH** side. **EXACT of ORIGINAL. For tractors;** 8N (1948 TO 1952).

NAA16486A
\$38.99

Bracket, rear running board. **RH** side. **EXACT of ORIGINAL. For tractors;** NAA (1953 TO 1954).

8N16470
\$19.50

Bracket, front running board. **RH** or **LH** side. **EXACT of ORIGINAL. For tractors;** All Except Select-O-Speed models (1948 to 1964).

355471S
\$1.20

Bolt, running board to running board bracket. For tractors; 8N, NAA, (1948-1954).

355471-KIT
\$18.14

Bolt kit, running board to running board bracket. Kit includes 8 running board bracket bolts, nuts & washers. For tractors; 8N, NAA (1948-1954).

REPLACES

Tool Box

8N17005
\$35.61

Tool box assembly. For tractors: 8N (1948-1952).

REPLACES

Bumpers & Hardware

311541OE
Call for Price

Bumper assembly with four bars for extra protection. Made to take rugged service. Welded and riveted construction. Exact copy of the original OEM bumper. Painted red. For tractors 9N, 2N, 8N, NAA, 600, 800.



BU1021
\$194.49

Bumper kit, for axle mount, painted red. For tractors 9N, 2N, 8N, NAA, 600, 800 (to 1964); 2000, 3000 (1965 & up); 2600, 3600, 4600 (1975 & up). (Kit contains 1-BU10211R grill & 2-BU10212R mounting arms)



D8NN17750AA
\$148.67

Bumper. High quality bumper complete with mounting brackets. Mounts to axle. Units painted blue. For tractors 2000, 3000 (1965 & up); 2600, 3600, 4100, 231, 233, 333, 531 (1975 & up).



311541HD
\$105.74

Bumper with four bars for extra protection. For tractors 9N, 2N, 8N, NAA, 600, 800.



BU1023
\$226.56

Bumper kit, for frame mount, painted red. For tractors 4000, 4500, 5100, 7100 (1965 & up), 5600, 6600, 7600 (1975 & up). (Kit contains 1-BU19215 mounting arms)



350790-KIT
\$12.09

Bolt kit, front axle bolt kit with bumper, contains; 2-3.4" bolts, 2-4" bolts, 4-351505S8 washers & 4 hex nuts. For tractors; 9N, 2N, 8N, NAA, 600, 800, (1939-1957).

REPLACES

Individual Grills & Parts

9N8206C
\$384.38

Radiator grill assembly, with **ROUND** grill bars. For tractors: 9N {early 1941}. **MADE EXACTLY LIKE THE FORD ORIGINAL.**



9N8206D
\$320.33

Radiator grill assembly, with **TEAR DROP** grill bars. For tractors: 9N, 2N.



8N8204DC
\$320.33

Radiator grill assembly, with **TEAR DROP** grill bars. For tractors; 8N, (1948-1952). **MADE EXACTLY LIKE THE FORD ORIGINAL.**

8N8204OE
\$117.08

Radiator grill assembly. Manufactured to restoration standards.



8N8204
\$50.55

Radiator grill assembly. Aftermarket version of grill.



C9NN8A163AG
\$24.92

Upper grill insert, plastic, has fixed Ford letters. For tractors 2000, 3000 (except 3400 and 3500), 4000, 5000 (2/1971-1975); 4200 (2/1971-1975); 5200, 7200 (2/1971-1975).




C7NN8A067A
\$1.26

Clip, radiator grill. For tractors 2000, 3000, 4000, 5000, 7000 (1965-1975); 5600, 6600, 7600 (1975-1981).



C3NN8200A
\$121.61

Grill. For tractors 2000, 4000 American made (1962-1964).



D5NN8200A
\$61.62

Grill screen, metal construction, painted black. Has white plastic emblem attached which has Ford lettering. For tractors 2600, 3600, 4100, 4600, 5600, 6600, 7600 (1975-1981).



C7NN8N043A
\$4.44

Knob, used on radiator grill, choke control & lighting. Fits all models 1939-1964; radiator grills on 2000, 3000, 4000, 5000, 7000 (1965-1975). Replaces 9N9703B.



D1NN8151A
\$24.92

Lower grill insert, plastic, for tractors without inset headlights. For tractors 2000, 3000 (except 3400 and 3500) (4/1968-1975); 4000 (6/1968-1975); 4200 (2/1971-1975); 5200, 7200 (4/1968-1975).



412575
\$5.25

Thumb screw for front grill, 5/16"-18. Fits tractors 5200, 7200 (1965-1975).



REPLACES

Hood Parts For 9N, 2N, 8N

8N16612
\$345.38

Hood includes battery cover. For tractors 9N, 2N, 8N. When used on 9N & 2N, also order air cleaner door 8N9661.



8N16618FR
\$68.48

Hood side panel, lower right. For tractors 9N, 2N, 8N.



8N16619FL
\$68.48

Hood side panel, lower left. For tractors 9N, 2N, 8N.



9N16625-56
\$15.24

Latch kit, contains battery door latch and handle w/stud. For tractors 9N, 2N, 8N.



9N16651-89
\$15.18

Hinge kit, contains hinge half for battery door and hood plus pin. For tractors 9N, 2N, 8N.




9N16938C
\$49.38

Battery door, less latch & hinge. For tractors 9N, 2N, 8N.




11A16758A
\$7.25

Rubber bumpers for gas filler lid door (set of 4). For tractors: 9N, 2N, 8N (1939-1952).




20311-KIT
\$3.65

Hood bolt kit, hood side panel to hood bolt, nut & washer. For tractors: 9N, 2N, 8N {1939-1952}.



350782-KIT
\$6.05

Bolt kit, hood side panel to axle support bolt, nut & washer kit with dog point **EXACT of ORIGINAL.** For tractors; 9N, 2N, 8N (1939-1952).



REPLACES

Radiator Shell

C5NN8N202L
\$282.96

Radiator shell assembly. For tractors 4000, 5000, 6000.



MISCELLANEOUS

REPLACES

Hood Panels & Parts

D3NN16626L
\$73.49

Hood panel assembly LH. For tractors 2600, 3600, 3900, 4600, 231, 233, 333, 335, 515, 532 (1975-3/1976); 420, 535 (1975-9/1978).

**D7NN16626A**
\$67.79

Hood panel assembly, engine LH side with AC. For tractors 4600 (1977-1981); 2810, 2910, 3910, 4610, 4610SU (1981-1/1983).

D5NN16626B
\$68.04

Hood panel, engine LH side, vertical exhaust, without cab. For tractors 5100 (1965-1975); 5600 (1975-3/1976); 5900 (1985-10/1991); 660, 7600 (1975-3/1976).

**D5NN16N768B**
Call for Price

Hood, engine RH. For tractors 5100, 7100 (1965-1975); 5600, 6600, 7600 (1975-1981).

D6NN16N644A
\$6.29

Handle assembly, engine hood RH side. For tractors 2000, 3000, 4000, 5000, 7000 (1965-1975); 2600, 3600, 3900, 4600, 231, 233, 333, 335, 515, 531, 532 (1975-1980); 420, 535 (1975-1978); 5600, 6600, 7600 (1975-1980); 2310, 2610, 2810, 2910, 3610, 4110, 4140, 4610 (1981-2/1990); 5610, 5910, 6610, 7610 (1981-10/1991); 3230, 3430, 3930, 4130, 4630 (3/1990-); 4830, 5030 (7/1990-).

**C5NN16N655A**
\$0.63

Rubber pad, hood to shell and rear panel. For tractors 2000 to 7000 (1965-1975); 2600 to 7600 (1975-1981); 2310 to 4610 (1981-2/1990); 5110 to 7710 (1981-1991); 7910, 8210 (1982-10/1991); 3230 to 4630 (1990-1994); 4830, 5030 (1990-1992); 7010, 8160 to 8560 (7/1995-).



REPLACES

Side Panels and Hood Parts

C3NN16652B
\$117.08

Side panel assembly, front RH lower. For tractors NAA, 600, 700, 800, 900, 2000, 4000 (1953-1964).

**C3NN16653B**
\$117.08

Side panel assembly, front LH lower. For tractors NAA, 600, 700, 800, 900, 2000, 4000 (1953-1964).

**354177S**
\$1.80

Bumper, hood tip center panel rubber bumper. For tractors: NAA, Jubilee, 501, 600, 601, 700, 701, 800, 801, 900, 901 (1953-1962).

**354117S4**
\$4.85

Bumper, hood tip center panel rubber bumper kit (4 per pkg). For tractors: 601, 701, 801, 901, (1957-1962).

354177S6
\$7.25

Bumper, hood tip center panel rubber bumper kit (6 per pkg). For tractors; NAA, 600, 700, 800, 900 (1953-1957).

REPLACES

Hood Emblems

2N16600
\$19.74

Two piece emblem set, includes 355870-S speed nuts. Cast aluminum, dull finish with black outline and lettering. For tractors 9N & 2N.

**8N16600B**
\$16.17

One piece emblem, includes 350836-S32 speed nuts. Cast aluminum, dull finish with red outline and lettering. For 8N.

**8N16600A**
\$38.45

Hood emblem, Ford name. Bright metal with red enamel background, bright lettering. For 8N (1948-1952).

**NAA16600A**
\$52.79

Hood emblem with mounting hardware. For NAA "Golden Jubilee".

**311231**
\$51.02

Hood emblem with mounting screws. For tractors 501, 600, 601, 701, 800, 801, 861, 900, 901 (1953-1962); LCG & industrials 1801, 2031, 4030, 4031, 4040, 4140 (1958-1964). Replaces CONN16600 D, E, F.

**NCA16600A**
\$58.08

Hood emblem, with mounting screws. For 600 (1955-1960).



NDA16600A Hood emblem, with mounting screws. For 800
\$58.08 (1955-1960).

REPLACES Fenders, Hardware, & Brackets

FF101S Fender panel, less mounting brackets. Has
\$117.86 raised. "FORD" script imprint. Fit **LH or RH**
SIDE OF TRACTORS; 9N, 2N, 8N(1939 TO
 1942);Row crop high clearance models 700,
 900(1957 to 1962).

D5NN16312LRS Rear fender with mounting bracket. Has raised
\$155.84 "FORD" script imprint. Fits **LH or RH** SIDE OF
TRACTORS; 501, 601, 701 except high
 clearance, 2000, 4000, (1958 to 1964); 2000,
 3000, 4100, 4110, 4200, (1965 to 1975); 2600,
 3600, 4100, 4600SU, 231, 335, 420, 515, 531,
 532, 535, (1975 TO 1981); 2310, 2610, 2810,
 2910, 3610, 3910, 4110, 4610, 230A, 530A,
 (1981 TO 1990).

E1NN16315DA Rear fender skin, less mounting
\$78.32 bracket. If bracket is needed,
 order TISCO universal bracket
 #UB16388EB. Fender skin fits LH
 or RH side. For tractors 501, 601,
 701 (except HiClear), 2000, 3000,
 4100, 4110, 4200 (1965-1975);
 2600, 3600, 4100, 4600SU, 231,
 335, 420, 515, 531, 532, 535
 (1975-1981); 2310, 2610, 2810,
 2910, 3610, 3910, 4110, 4610,
 230A, 530A (1981-1990).



FF101 Fender panel, less mounting
\$68.43 brackets. For tractors 9N, 2N, 8N
 (1939-1942); row crop
 high-clearance models 700, 900
 (1957-1962).



8N16312 Rear fender, dished type with
\$94.14 mounting bracket. Fits tractors
 with dished fenders 9N, 2N, 8N
 (1939-1952); row crop high
 clearance models 700, 900
 (1957-1962).



UB16388EB Mounting bracket for fender skin
\$37.26 E1NN16315DA. Fits LH or RH side. Center hole
 bottom bracket 5". Universal.

D5NN16312LRS Rear fender with mounting
\$113.13 bracket. Fits LR or RH side on
 tractors 501, 601, 701 (except
 HiClear), 2000, 4000 (1958-1964);
 2000, 3000, 4100, 4600SU, 231,
 335, 420, 515, 532, 535
 (1975-1981); 2310, 2610, 2810,
 2910, 3610, 3910, 4110, 4610,
 230A, 530A (1981-1990).



355310-KIT Bolt kit, rear fender bracket to axle housing, bolt,
\$30.20 nut & washer kit (set of 4) For tractors: 8N, NAA
 (1948-1954).

REPLACES Counter Stool

*COOL STOOL "FORD" LOGO Chrome tubular steel frame
 Durable 12 guage vinyl seat White vinyl top with black side
 band*

401T Stool, 1 ring, swivel base, Black & Red "FORD"
\$142.40 logo on white.

REPLACES Hex Nuts



34670S36 Std. hex nut, 7/16" -14.
\$0.09

34671S36 Hex nut, 7/16" -20 x 11/16".
\$0.09

33806S7 Nut, 5/8"-18. For NCA1020B & C5NN1050E
\$0.39 wheels.

45302S36 Nut. For 220956 rotary cutter bolt.
\$1.08

REPLACES Washers

34806S36 Lock washer, 5/16".
\$0.05

34808S36 Lock washer, 7/16".
\$0.06

34811S36 Lock washer, 5/8".
\$0.09

MISCELLANEOUS

REPLACES

Plated Hardware Items Guard
& Plow Bolts

GB3711

7/16" -14 x 1-1/4", #3 head.

300369S36

7/16" -14 x 1-1/2", #3 head.

301175S36

7/16" -14 x 1-3/4", #3 head.

REPLACES

Grease Gun & Parts

C3NN17125A

3-way fill cartridge gun.

B9NN17A019A

12" flex hose.

GM23

6" pipe for grease gun.

REPLACES

Fabric Cement



FC302

6 oz. container. Packed twelve in attractive display carton.

REPLACES

Air Conditioning Compressors

D6NN19D623A

Air conditioning compressor, replacement for York compressor, less clutch. 6-bolt type 2. Has Rotalock hose fitting ports, left hand suction with no high pressure relief valve. Replaces both 9 and 10 CID units. Replaces D3NN19D623A.

D7NN19D623A

Air conditioning compressor, replacement for Tecumseh compressor, less clutch. Has Rotalock hose fitting ports, left hand suction with no high pressure relief valve. 10 CID.